

Bm Fw Mathias Eberl killed in crash of D0217E-4 U5+LM 5466 of 4/KG2 on 17/18-1-1943.

Aircraft crashes on return following engine damage from mining sortie to Thames Estuary at

Kapelle by Goss. Ff Ltn Karl Hense inj., B. Gef Eberhard Weiss +, Bf Ofw Karl Hochstuhl inj.

Source KG2 history by Ulf Balke.